

Feuille1

Pas monture M100B - ESCAP - P530

Sid day

86164,0916

gear	motor	total	P530	
	200,00	12	2400	100,000 pas/tour
	Moteur		Monture	
32,00 upas/pas		3,60 °/pas		5,400 "/pas
2,79 pas/seconde		405,00 "/upas		0,169 "/upas
speed	/sidereal	1,00 tour		0,150 °/tour
				EEPROM
1	89,132258 upas/seconde		15,041 "/s	000DB206
2	178,26452		30,082 "/s	0006D903
5	445,66129		75,205 "/s	0002BD34
10	891,32258		150,411 "/s	00015E9A
20	1782,64515		5,014 arcmin/s	0000AF4D
50	4456,61288		12,534 arcmin/s	0000461E
100	8913,22575		25,068 arcmin/s	0000230F
200	17826,45150		50,137 arcmin/s	00001187
500	44566,12875		2,089 °/s	00000703
1000	89132,25750		4,178 °/s	00000381

23 56 4,09 86164,09 0,9972695787037037 7680000,00 360,000 00753000